



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor *P*

Minerals Regulatory Program

Date of Report:

July 15, 2010

Mine Name: Quarry (Little Salt Creek Gypsum)

Operator Name: Cox Transport Incorporated

Permit number: S0230096

Inspection Date: 07/13/2010

Time: 1:40 – 2:00 PM

Inspector(s): Wayne Western

Other Participants: none

Mine Status: Active

Weather: 88 F partly sunny
skies

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: This was a routine inspection

Inspection Summary:

The bond is due for escalation in August 2010, the Division will send a separate letter to the Permittee informing them that the bond will be escalated.

The Permittee did not submit the annual reports for 2009 and the Division will follow up with a letter.

The site appeared to be stable.

The Permittee stated in the 2008 annual permit that 1 acre had been reclaimed. If the Permittee wants to reduce the number of bonded acres then they must go through the bond release process.

Conclusions and Recommendations: Operator now is now in compliance. OGM will continue to monitor site when in the area.

Inspector's Signature _____ **Date:** _____

whw:pb

cc:

Brent C. Cox
Jerry_Mansfield@BLM.gov

O:\M023-Juab\S0230096-CoxTransportation\inspections\Insp_S0230096_07-15-2010.doc